SUPPLY LIST FOR WELDING CLASSES

- 1. Welding Hood with lens "Shade 9" or darker
- 2. Mono-goggles
- 3. Safety Glasses
- 4. Leather Gloves
- 5. Leather Work Boots/Shoes
- **6.** Long Sleeve Cotton or Denim Shirt (no synthetic materials)
- 7. <u>Cotton</u> or <u>Denim</u> long trousers (<u>no synthetic materials</u>)
- 8. Striker
- 9. Chipping Hammer
- **10.** File
- 11. Wire Brush
- 12. C Clamp
- 13. Soapstone
- 14. Tool Container (Bucket)
- 15. Whip (Stinger)
- 16. 4 ½" Hand Grinder & Wheels
- 17. 10" Adjustable (Crecent) Wrench
- 18. Pliers
- 19. Allen Wrench Set
- 20. Phillips & Flat Blade Screw Drivers
- 21. Tig Torch (Heliarc Students)

Supplies are estimated to cost \$150 to \$250 depending upon the supplies each student already owns.